



This is the upper gib for the Linear Bearings. It goes under the Gib Plate. You need 2 of these for each Axis on your machine. 6 parts for a Alfamill and 8 for a CNC router. I have also made these out of HDPE and I would say that it works just as good as Acetal if not better. I have not tried Teflon mostly because of cost. It should work great too.