

# Alfahobbies AlfaMill Z Axis Slide

The Z Axis Slide is the part that slides up and down the column, moving the head up and down. It is made from a 3030 80/20 extrusion. 3030 stands for 3 inches by 3 inches. Make it 6 inches long. Cut it so it is square within 1 degree on each end. There are 4 holes in each end of the extrusion. Tap all 8 holes 5/16-18.

