



The .500 side of this part has a +/- .005 tolerance. This is to insure that it fits into a groove in the Linear Bearing. The Groove in the Linear Bearing should be .510 minimum wide. As long as it fits in that groove it should be fine. I have also made these out of HDPE and it works great. I have not tried teflon for this part but it should too.